

Asbestos Registry

Type of Facility (e.g., healthcare, school, government building, crown building): Healthcare

Name of RHA, School District or Crown (if applicable): Kelsey Trail Health Region

Owner Name (if applicable): Kelsey Trail Health Region

Location (Street address, City): 512 1st Avenue South

Facility Name (if applicable): Kelvington Hospital

Date of Submission: November 28, 2014

Contact Person: Trent Mitchell Title: Director of Information Management & Building Services

Telephone: 306-752-7594 Email: tmitch@kthr.sk.ca

1. Type of Asbestos-Containing Material [ACM] (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (optional)
Roof Drain Pipe	Basement Crawl Space	80% Chrysotile, 20% Non-Fibrous	Medium - as staff can be working in this area.	Condition- Excellent – require caution when working in area.
Elbow Hot Water Supply	Basement Crawl Space	60% Chrysotile, 5% Glass Fiber, 20% Cellulose, 15% Non-Fibrous (Binder) 3-Condition-Friable 4 -Condition- Poor approaching friable 20 Condition Fair 235 Condition- Excellent	Medium - as staff can be working in this area.	3 Pipe fittings-Medium-Condition – Further inspection pending, caution when working in area.
Floor Tiles	Main Floor		Medium - the floor tiles are where staff and the public walk.	Condition- Excellent

