

Asbestos Registry

Type of Facility (e.g., healthcare, school, government building, crown building): Healthcare

Name of RHA, School District or Crown (if applicable): Kelsey Trail Health Region

Owner Name (if applicable): Kelsey Trail Health Region

Location (Street address, City): Windsor Avenue Porcupine Plain

Facility Name (if applicable): Porcupine Carragana Hospital

Date of Submission: November 28,2014

Contact Person: Trent Mitchell Title: Director of Information Management & Building Services

Telephone: 306-752-7594 Email: tmitch@kthr.sk.ca

1. Type of Asbestos-Containing Material [ACM] (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (optional)
Elbow Air Handling Unit St. Line	Boiler Room – West Wall	50% Chrysotile, 50% Non-Fibrous	Medium - staff can be working in this area.	Pipe fittings-8 small - condition-Fair – further inspection pending
Top BLR- Exhaust Breeching	Boiler Room	55% Amosite, 45% Non- Fibrous	Medium - staff can be working in this area.	Pipe fittings-2 small - Pipe fittings-4 small - Condition fair further inspection pending
Elbow Water Line	Boiler Room – North Wall	40-50% Chrysotile, 35% Non-Fibrous, 10% Cellulose, 5% Glass Fibers	Medium - as staff can be working in this area.	Pipe fittings-33 small, 22 Medium, 4 large- condition-- Excellent
Flange Joint Gasket	Emergency Generator Set South Side	40% Chrysotile, 20% Non-Fibrous, 40% Glass Fiber	Low - item is behind locked doors.	
Expansion Joint South Side	Emergency Generator Set – South Side	95% Chrysotile, 5% Non-Fibrous,	Low – item is behind locked doors.	Condition – poor – further inspection pending

Room 104 – in Fire Wall	Block Wall	3-5% Asbestos, 95% Vermiculite	Low - due to the building materials and covered with paint.	Condition-Excellent
-------------------------	------------	--------------------------------	---	---------------------

