

Asbestos Registry

Type of Facility (e.g., healthcare, school, government building, crown building): Healthcare

Name of RHA, School District or Crown (if applicable): Kelsey Trail Health Region

Owner Name (if applicable): Kelsey Trail Health Region

Location (Street address, City): 806-97th Avenue Tisdale

Facility Name (if applicable): Sasko Park Lodge

Date of Submission: November 28, 2014

Contact Person: Trent Mitchell Title: Director of Information Management & Building Services

Telephone: 306-752-7594 Email: tmitch@kthr.sk.ca

1. Type of Asbestos-Containing Material [ACM] (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (optional)
Line Insulated Steam Line overhead	Maintenance Room South Side	80% Chrysotile, 20% Non-Fibrous	Low - Basement locked door assess, up high. All pipes are insulated, can be accessed.	Pipe runs-164-small, 3 medium, 1 large- Condition poor – further inspection pending. Pipe runs-30small- Condition poor – further inspection pending. Pipe runs-330 small, 76 medium- Condition fair. Pipe runs-976 small, 150 Medium. 99 large- Condition- Excellent
Stipple Ceiling Typical	Dining Room-TV Area	1-2% Chrysotile, 86% Non-Fibrous, 1-2% Cellulose, 10% Paint	Medium - sealed up high, can be accessed.	Condition- Excellent
Floor Tile	Suite North East Center Area	4-5% Chrysotile, Non-Fibrous	Low - Can be locked, accessible.	This is 60% of total flooring. Condition fair – further inspection pending.

